

| Ref. No. | Part No. | Description | Reqd. No. PC50 | No. Used on | | News No. |
|----------|----------------|-----------------------------------|----------------|--------------|-------|----------|
| | | | | From | To | |
| 1 | 16100-063-004 | CARBURETOR ASSY. | 1 | PC50-1000001 | | |
| 2 | 16194-063-004 | CAP, cable | 1 | PC50-1000001 | | |
| 3 | 16118-063-004 | ADJUSTER, cable | 1 | PC50-1000001 | | |
| 4 | 16119-063-004 | TOP..... | 1 | PC50-1000001 | | |
| 5 | 16171-044-004 | WASHER, top | 1 | PC50-1000001 | | |
| 6 | 16185-044-004 | SPRING, throttle..... | 1 | PC50-1000001 | | |
| 7 | 16156-044-004 | PLATE, needle clip | 1 | PC50-1000001 | | |
| 8 | 16157-044-004 | CLIP, needle..... | 1 | PC50-1000001 | | |
| 9 | 16151-063-004 | NEEDLE, jet | 1 | PC50-1000001 | | |
| 10 | 16141-063-004 | VALVE, throttle | 1 | PC50-1000001 | | |
| 11 | 16199-063-004 | PLATE, clip..... | 1 | PC50-1000001 | | |
| 12 | 16181-001-004 | SPRING, air screw..... | 1 | PC50-1000001 | | |
| 13 | 16162-044-004 | SCREW, air | 1 | PC50-1000001 | | |
| 14 | 16181-250-004 | SPRING, throttle stop | 1 | PC50-1000001 | | |
| 15 | 16163-063-004 | SCREW, throttle stop | 1 | PC50-1000001 | | |
| 16 | 16164-040-004 | SCREW, drain..... | 1 | PC50-1000001 | | |
| 17 | 16189-066-004 | WASHER, fiber, 6.2 ϕ | 1 | PC50-1000001 | | |
| 18 | 16122-063-004 | FLOAT | 1 | PC50-1000001 | | |
| 19 | 16197-063-004 | PACKING | 1 | PC50-1000001 | | |
| 20 | 16173-063-004 | O-RING, 43 ϕ | 1 | PC50-1000001 | | |
| 21 | 16196-063-004 | PLATE, arm pin set | 1 | PC50-1000001 | | |
| 22 | 16126-063-004 | PIN, arm | 1 | PC50-1000001 | | |
| 23 | 16127-063-004 | ARM, float..... | 1 | PC50-1000001 | | |
| 24 | 16178-548-004 | O-RING, 3.2 ϕ | 1 | PC50-1000001 | | |
| 25 | 99114-063-0500 | JFT, main (#50) | 1 | PC50-1000001 | | |
| | 99114-063-0520 | JET, main (#52) | 1 | PC50-1000001 | | |
| | 99114-063-0550 | JET, main (#55) (S.T.D.) | 1 | PC50-1000001 | | |
| | 99114-063-0580 | JET, main (#58) | 1 | PC50-1000001 | | |
| | 99114-063-0600 | JET, main (#60) | 1 | PC50-1000001 | | |
| 26 | 16183-063-004 | JET, needle | 1 | PC50-1000001 | | |
| 27 | 93500-09005-0A | SCREW, pan, 3 \times 5..... | 2 | | | |
| 28 | 93500-04012-0A | SCREW, pan, 4 \times 12 | 2 | | | |
| 29 | 94111-03000 | WASHER, spring, 3 mm | 1 | | | |
| 30 | 94111-04000 | WASHER, spring, 4 mm | 2 | | | |
| 31 | 95001-35140-10 | TUBE, fuel, 3.5 \times 140..... | 1 | | | |