

M 9

F - 6


Steering stem

Tige de direction

Steuerkopfschaft

Varilla de dirección

FR.



MX23 F0600B

Item d'entretien	T.D.R.	N° de réf.	N° de pièce	Description	N° de requis								N° de série	Code de zone	
					XR000										
					RF	RG	RH	RJ	RK	RL	RM	RN			
		12)	53600-404-611	ANTIVOL DE DIRECTION COMP.....	1	-	-	-	-	-	-	-	5000096	-----	D,SA,U
					-	1	1	1	1	1	1	1	-----	-----	B,DK,ED,SD U,2B
		13	53603-051-000	RIVET, 4.1MM.....	1	1	1	1	1	1	1	1	-----	-----	B,DK,ED,SA SD,U,2B
		14	53604-098-940	RONDELLE, 4.5MM.....	1	1	1	1	1	1	1	1	-----	-----	B,DK,ED,SA SD,U,2B
		15	90107-KFO-000	BOULON DE BRIDE, 8X40.....	4	4	4	-	-	-	-	-			
			96300-08040-00	BOULON DE BRIDE, 8X40.....	-	-	-	4	4	4	4	4			
		16	91015-425-831	ROULEMENT SUPERIEUR DE TUYAU PRINCIPAL (TOYO)	2	2	2	2	2	2	2	2			
			91015-425-832	ROULEMENT SUPERIEUR DE TUYAU PRINCIPAL (NACHI)	2	2	2	2	2	2	2	2			
		17	96300-06012-00	BOULON DE BRIDE, 6X12.....	-	-	-	1	1	1	1	1			

1991.07.10

E

M9

1991.07.10

E

M9