


Do not apply commercially available carburetor cleaners to the inside of the throttle bore, which is coated with molybdenum.





## **ASSEMBLY**



6-59