Instruments (Continued)

| Failure Information

Indication	Explanation	Remedy
\tilde{\	When your motorcycle has a problem with the PGM-FI system	Reduce speed and have your motorcycle inspected by your dealer as soon as possible.
<i>P</i> !	CBR1000S1 When your motorcycle has a problem with the ÖHLINS Smart EC system	Reduce speed and have your motorcycle inspected by your dealer as soon as possible.