

Ref. No.	Part No.	Description	Reqd. No. PC50	No. Used on		News No.
				From	To	
1	11431-063-000	COVER, dynamo.....	1	PC50-1000001	
2	90201-044-000	NUT, 10 mm.....	1	PC50-1000001	
3	90426-001-000	WASHER, magneto fixing	1	PC50-1000001	
4	31121-063-004	FLYWHEEL (Nippon Denso)..... (Used in General)	1	PC50-1000001	
	31121-063-601	FLYWHEEL (Nippon Denso)..... (Used in England)	1	PC50-1000001	
	31121-063-621	FLYWHEEL (Nippon Denso)..... (Used in France)	1	PC50-1000001	
5	31100-063-004	A.C. GENERATOR ASSY., flywheel ... (Nippon Denso) (Used in General)	1	PC50-1000001	
	31100-063-601	A.C. GENERATOR ASSY., flywheel ... (Nippon Denso) (Used in England)	1	PC50-1000001	
	31100-063-621	A.C. GENERATOR ASSY., flywheel ... (Nippon Denso) (Used in France)	1	PC50-1000001	
6	30205-044-014	FELT, oil (Nippon Denso)	1	PC50-1000001	
7	31632-063-004	COIL, lamp (Nippon Denso)	1	PC50-1000001	
		(Used in General)				
	31632-063-601	COIL, lamp (Nippon Denso)	1	PC50-1000001	
		(Used in England)				
	31632-063-621	COIL, lamp (Nippon Denso)	1	PC50-1000001	
		(Used in France)				
8	30541-063-004	COIL, primary (Nippon Denso).....	1	PC50-1000001	
9	30207-063-004	SCREW, breaker set (Nippon Denso) ...	1	PC50-1000001	
10	30208-063-004	WASHER, spring (Nippon Denso)	1	PC50-1000001	
11	30209-063-004	WASHER, plain (Nippon Denso)	1	PC50-1000001	
12	30202-063-004	BREAKER ASSY., contact	1	PC50-1000001	
		(Nippon Denso)				
13	32957-063-010	CLAMPER, dynamo cord	1	PC50-1000001	
14	32956-063-300	GROMMET, dynamo cord	1	PC50-1000001	
15	32958-044-000	COVER, wire harness	1	PC50-1000001	
16	93500-04020-0A	SCREW, pan, 4×20	4	