


F-15
AIR CLEANER



| Service Item | F.R.T. | BOM Of Group Number: F-15 Model :: Splendor+ (Sep, 2003) | | | |
|------------------------------|--------|--|----------------|-----------------------------|------|
| | | Ref No. | Part Number | Description | Req. |
| CASE COMP. AIR CLEANER | 0.3 | 1 | 17210-KCC-940 | CASE COMP. AIR CLEANER | 1 |
| ELEMENT A, AIR CLEANER | 0.2 | 2 | 17211-KCC-900L | ELEMENT A, AIR CLEANER | 1 |
| HOLDER, ELEMENT | -- | 3 | 17212-KCC-900 | HOLDER ELEMENT | 1 |
| ELEMENT 'B' AIR CLEANER | -- | 4 | 17212-KCC-902 | RUBBER ELEMENT SEAL | 1 |
| COVER, AIR CLEANER CASE | -- | 5 | 17213-KCC-900L | ELEMENT B, AIR CLEANER | 1 |
| DUCT, AIR CLEANER INLET | -- | 6 | 17219-KCC-940 | SEAL,AIR CLEANER CASE | 1 |
| TUBE, AIR CLEANER CONNECTING | -- | 7 | 17222-KCC-902 | FILTER | 1 |
| | | 8 | 17222-KCC-940 | COVER,AIR CLEANER CASE | 1 |
| | | 9 | 17224-KCC-940 | WATER GUARD, FRONT | 1 |
| | | 10 | 17234-KCC-940 | TUBE AIR CLEANER DRAIN | 1 |
| | | 11 | 17251-KCC-940 | DUST AIR CLEANER INLET | 1 |
| | | 12 | 17253-KCC-900 | TUBE AIR CLEANER CONNECTING | 1 |
| | | 13 | 1725A-323-000 | BAND 'A' CONNECTING TUBE | 1 |
| | | 14 | 17369-198-770 | CLIP BREATHER TUBE | 2 |
| | | 15 | 18651-KCC-940 | TUBE 'A' ASV | 1 |
| | | 16 | 61312-149-300 | BOOT, HEADLIGHT BRACKET | 1 |
| | | 17 | 83407-KCC-901 | CUSHION BAND BATTERY | 1 |
| | | 18 | 90111-187-010 | BOLT, HEX SPL. 6MM | 2 |
| | | 19 | 90111-187-0201 | WASHER SPL., 8.5 (Ø20) | 2 |
| | | 20 | 93500-04025-0A | SCREW PAN, 4 X 25 | 1 |