


F-2

METER

Ref. No.	L.O.N.	(Relative ref. Number)	Description	F.R.T.
1	6161G3	(2,3,4)	BULB, METER	0.2
.NOTE: Same time for two units or more				
5	8121A1	(10)	METER ASSY., COMBINATION	0.8
6	8121B7		LENS, METER	0.8
7	8121A2		METER, COMBINATION	1.0
9	6161G4		SOCKET ASSY., METER BULB	0.7
12	6111C3		RELAY, WINKER	0.5
14	811160		CABLE, SPEEDOMETER	0.6



Ref. No.	Part No.	Description	Reqd. QTY		Serial No.	Parts catalogue code
			AFS110	MCS MD		
			L	L		
1	34905-K09-C01	BULB, WEDGE BASE(T6.5 3W) ...	1	1		
2	34908-KYA-601	BULB, WEDGE BASE(T10) (12V 3.4W)	2	2		
3	34910-GFM-901	BULB, WEDGE BASE(T10) (12V 1.7W)	3	3		
4	34918-GFC-951	BULB, WEDGE BASE (T6.5 12V 1.7W)	4	4		
5	37200-K71-MB1	SPEEDOMETER ASSY. (KPH) .....	1	1		
	37200-K71-MA1	.....	-	1		
6	37202-K09-C01	LENS, SPEEDOMETER .....	1	1		
7	37210-K71-M01	SPEEDOMETER COMP. ....	1	1		
8	37215-KVJ-911	CLAMP, CORD .....	1	1		
9	37224-K71-MB1	SOCKET COMP. ....	1	1		
	37224-K71-MA1	.....	1	1		
10	37302-K09-C01	PLATE COMP., REFLECTING .....	1	1		
11	37305-GFM-901	SCREW-WASHER, 3X22 .....	3	3		
12	38301-GBG-911	RELAY COMP., WINKER (PT. MITSUBA)	1	1		
13	38306-KK4-000	SUSPENSION, WINKER RELAY (MITSUBA)	1	1		
14	44830-KW-640	CABLE ASSY., SPEEDOMETER .....	1	1		
15	90035-GFM-901	SCREW-WASHER, SPECIAL, 4X12 ..	2	2		
16	91256-KK3-840	O-RING, 10X1.5 .....	1	1		
17	93903-24320	SCREW, TAPPING, 4X12 .....	1	1		
18	93903-25310	SCREW, TAPPING, 5X16 .....	2	2		