


F-3

SPEEDOMETER



Service item	F.R.T.
COVER COMBINATION SWITCH	0.1
SPEEDOMETER ASSY.	0.3
•SOCKET COMP.	
•CABLE ASSY. SPEEDOMETER	0.1
KEY SET	0.5

REF. PART NO.	DESCRIPTION	REQ'D. NO. OLD	REQ'D. NO. NEW	REF. PART NO.	DESCRIPTION	REQ'D. NO. OLD	REQ'D. NO. NEW
1	34902-GA7-008			1	BULB WEDGE BASE (6V-3W)	2	2
2	34908-GA7-008			2	BULB WEDGE BASE (6V.-1.7W)	1	1
3	35010-KE6-833			3	KEY SET	1	1
4	35100-KE6-832			4	SWITCH ASSY., COMBINATION	1	1
5	35121-402-811			5	KEY, BLANK TYPE 1 (OPTIONAL)	-	-
6	35122-402-811			6	KEY, BLANK TYPE 2 (OPTIONAL)	-	-
7	37200-KE6-831			7	SPEEDOMETER ASSY.	1	1
8	37203-KE6-831			8	PACKING	1	1
9	37210-KE6-831			9	METER ASSY.	1	1
10	37212-KE2-880			10	STAY SPEEDOMETER	1	1
11	37610-KE6-831			11	CASE ASSY., METER UPPER	1	1
12	37617-KE6-831			12	CASE ASSY., METER LOWER	1	1
13	44830-324-710			13	CORD COMP.	1	1
14	44831-324-710			14	CABLE ASSY. SPEEDOMETER	1	1
15	44834-KB5-740			15	CABLE INNER	1	1
16	80101-283-000			16	RUBBER CABLE	2	2
17	90545-323-700			17	RUBBER RR., FENDER CUSHION	5	5
18	93500-04008-0A			18	WASHER 6.5X18	2	2
19	93901-24410			19	SCREW PAN 4X8	1	1
20	93901-24410			20	SCREW TAPPING 4X16	1	1
21	94021-06020			21	SCREW TAPPING 4X16	3	3
22	94111-06000			22	NUT CAP 6MM	2	2
					WASHER, SPRING, 8MM	2	2