


F-38

BATTERY

G12



Ref. No.	L.O.N.	(Relative ref. Number) Description	F.R.T.
1	610100	BATTERY	0.2
3	610105	CABLE, POSITIVE BATTERY	0.2
4	612115	CABLE, STARTER MOTOR	0.2
8	610110	CABLE, NEGATIVE BATTERY	0.2
9	615113	SWITCH, STARTER MAGNETIC	0.2

Ref. No.	Part No.	Description	Reqd. QTY GL150 1WH C	Serial No.	Parts catalogue code
1	31500-KYA-B01	BATTERY ASSY.(YTX7L-BS)	1		
2	32127-KVJ-911	CASE, FUSE(20A)	1		
3	32401-KVX-700	CABLE, STARTER MAGNETIC	1		
		BATTERY	1		
4	32410-KVX-600	CABLE, STARTER MOTOR	1		
5	32411-253-000	COVER, STARTER MOTOR TERMINAL	1		
6	32416-KGF-900	COVER, BATTERY TERMINAL	1		
7	32416-KM3-300	COVER, MAGNETIC SWITCH	1		
		TERMINAL	2		
8	32601-KVX-700	CABLE, BATTERY EARTH	1		
9	35850-KVX-701	SWITCH ASSY., STARTER MAGNETIC	1		
10	35856-KVX-601	RUBBER, SHOCK(MAGNETIC)	1		
11	35857-KVX-601	RUBBER B, SHOCK	1		
12	50380-KVX-600	BAND, BATTERY	1		
13	50383-KVX-600	GUARD, BATTERY	1		
14	83618-323-000	RUBBER, BATTERY BOX	1		
15	94002-06080-0S	NUT, HEX., 6MM	2		
16	94111-06800	WASHER, SPRING, 6MM	2		
17	95701-06014-08	BOLT, FLANGE, 6X14	2		
18	98200-22000	FUSE B(20A)	2		

3