


# F-2 Meter Compteur Indicador



3

Service item	F.R.T	Ref. N°	Part No.	Description	Qty. XL200	Serial No.	Note
CABLE, INNER.....	0.1	1	34908-GA7-701	BULB, WEDGE BASE (12V 3.4W) .....	3	.....	.....
CABLE ASSY., SPEEDOMETER.....	0.2	2	34908-MB9-871	BULB, WEDGE BASE (12V/1.7W) .....	1	.....	.....
• STAY, SPEEDOMETER		3	37200-KBB-901	SPEEDOMETER ASSY. (KPH) .....	1	.....	.....
• SOCKET COMP .	0.3	4	37223-KBB-901	SOCKET COMP .....	1	.....	.....
• SPEEDOMETER ASSY.		5	37243-MG2-000	RUBBER, SPEEDOMETER MOUNTING .....	2	.....	.....
		6	37618-MB2-008	CAP, SPEED ALARM CORD .....	2	.....	.....
		7	44830-KW8-900	CABLE ASSY., SPEEDOMETER .....	1	.....	.....
		8	44831-KV2-900	CABLE, INNER .....	1	.....	.....
		9	61317-KBB-900	STAY, SPEEDOMETER .....	1	.....	.....
		10	93700-05018-0G	SCREW, OVAL, 5X18 .....	1	.....	.....
		11	94021-06000-0S	NUT, CAP, 6MM.....	2	.....	.....
		12	94103-06000	WASHER, PLAIN, 6MM .....	2	.....	.....
		13	95701-06016-00	BOLT, FLANGE, 6X16 .....	2	.....	.....