
Balance each carburettor by turning
synchronizing bolt

Special Tool:

Pilot Screw Wrench : 07908-4220201

* No.1 carburettor becomes normal

After adjusting, snap throttle 2-3 times
inspect and adjust idling (2-12)

